



1、焊前预热: 400-450℃, 焊后冷却: 400-450℃, 40℃烘干60分钟

直径的3倍。

